



STATE OF NEW YORK
DEPARTMENT OF TRANSPORTATION
ALBANY, N.Y. 12232
www.nysdot.gov

STANLEY GEE
ACTING COMMISSIONER

DAVID A. PATERSON
GOVERNOR

April 22, 2010

Mr. Tom Biamonte
Shelby Crushed Stone, Inc.
10830 Blair Road
Medina, NY 14103

Geological Source Report Status: **Accepted**
Location: Shelby Crushed Stone, Inc.
Source No. 4- 16R,RFM
Shelby Center, NY

Dear Mr. Biamonte:

The 2010 Geologic Source Report Annual Module submitted for the proposed operating location noted above has been reviewed and accepted. The Geological Source Report Requirements for the 2010 season have been satisfied. However, if significant discrepancies between the report and the quarry operations are noted during field inspection, a revised report will be required. Please note there shall be no extension or alteration to the limits of the area of proposed operations without prior approval from this office.

Aggregate sources which satisfy all applicable requirements of Materials Method 29, issued July 2007 will appear on the Approved List of Sources of Fine and Coarse Aggregates. The Approved List is available on the Internet @

<https://www.nysdot.gov/divisions/engineering/technical-services/materials-bureau/fine-coarse-aggregates>

If the producer or the consulting geologist have any questions regarding these matters, they may call Mr. William Skerritt, or members of his staff in our Materials Bureau Engineering Geology Section at (518) 457-1038.

Very truly yours,

William Skerritt
Engineering Geology

WHS/RLW

File: 4- 16R,RFM

cc: Jim Jordon, Region 4 Materials Engineer

Brian Norensky, George L. Marshall, Engineering Geologists