

Shelby Crushed Stone Wells

Well Measurements

*Note: Well measurements are made to the top of the well casing
All measurements in feet*

Well Depth(ft)

Date	East	West	PZ1	PZ2	SG1
Ht. above grd.	2.50	1.50			
Bottom Depth	??	46.00	7.08	9.30	3.54
2/8/2019	8.70	9.70			
4/9/2019	6.30	8.60			
6/21/2019	17.20	13.20			
7/15/2019	27.44	13.42			
8/10/2019	28.75	13.40			
9/26/2019	29.68	13.85			
10/7/2019			7.08	9.30	3.54
10/18/2019	23.26	12.35	7.08	9.30	3.54
10/25/2019			7.08	9.30	3.54
11/1/2019			7.08	9.30	3.54
11/9/2019	27.02	13.38	7.08	9.30	3.01
11/15/2019			7.08	9.30	2.31
11/20/2019			7.08	9.30	2.21
12/5/2019	28.30	12.89	7.08	3.62	1.95
12/17/2019			4.54	2.55	1.70
12/27/2019			4.44	NR	1.83
1/3/2020	9.05	12.69	2.16	NR	1.66
2/3/2020	9.35	14.15	2.04	NR	1.74
3/3/2020	8.49	13.41	1.42	NR	1.33
4/1/2020	9.90	13.83	2.33	NR	1.83
4/6/2020			2.5	2.69	1.84
5/5/2020	9.64	14.41	2.43	2.68	1.83
6/3/2020	20.02	14.33	4.74	3.66	2.36
7/3/2020	29.34	13.91	*6.77	7.72	*3.52
8/6/2020	27.64	13.09	*6.86	8.20	*3.52
9/10/2020	29.97	12.99	*6.87	8.68	*3.52
10/9/2020	29.76	13.12	*6.91	8.94	*3.52
11/5/2020	29.80	13.81	*6.93	9.00	*3.52
12/23/2020	29.07	13.89	**6.95	9.06	*3.52
1/15/2021	9.90	13.93	**6.95	5.12	2.3
2/15/2021	19.35	13.82	**6.95	5.35	2.45
3/17/2021	9.91	14.38	4.05	2.84	2.32
4/27/2021	9.24	13.02	2.62	NR	1.96
5/21/2021	11.60	13.35	4.96	3.85	2.53
6/16/2021	28.34	13.13	6.16	6.39	*3.53
7/15/2021	23.85	12.58	*6.90	6.79	*3.53
8/16/2021	26.29	13.13	6.8	4.60	2.55

Note: wetland north of ditch is predominately without water

wetland north of ditch dry
"*****"

NR= No Reading - Limited Access
*= No Water
**=Well damaged. Pipe bent